## Project Report



PROTECTING POWER PLANT CHIMNEYS

San Juan Power Station

**Key facts about San Juan Power Station** 

- 2 x 350 MW and 2 x 550 MW coal fired power station
- Wet FGD on all four units
- No flue gas reheat
- All four existing chimneys with brick flues to be lined with Pennguard®

Pennguard® is a registered trademark of Ergon Asphalt & Emulsions, Inc.

Coal fired power station in the western United States prepares its four chimneys for wet stack operation by installing Pennguard® linings in the brick flues.

The San Juan Generating Station near the town of Farmington, New Mexico is a mine mouth power station with an installed capacity of 1,800 MW. Its four boilers, two of 350 MW and two of 550 MW each, fire coal with a sulfur content of 0.9 %. The power station has operated FGD plants for many years and it will now move to desulfurizing one hundred percent of its exhaust gas flow.


In the mid seventies, the San Juan Station was fitted with FGD plants using the Wellman Lord process. This early FGD system used four separate scrubber vessels per unit. In the late nineties, the FGD system was converted to a wet limestone process, upgrading the sulfur removal efficiency from 75 % to 90 %. The power station continued to bypass a portion of the gas stream around the FGD system.

Through the years of operating the San Juan chimneys with a mixed, partially desulfurized gas flow, it was found that the free standing brick chimney flues were subject to degradation especially in the mixing zones for treated and non-treated gas flows. In 2002 and 2003 the station installed Pennguard® linings in the lower part of the brick flues of the Unit 1 and Unit 2 chimneys.

With emissions regulations becoming more and more stringent, the San Juan Power Station, which is operated by Public Service of New Mexico but which is owned by nine utilities from five states, decided in 2006 to switch to fully desulfurized operation, eliminating any bypass around the FGD system.

In order to prepare the chimneys for low temperature wet stack operation, the owners also decided that the brick flues in all four chimneys would be protected by Pennguard® linings over their full height.

## **Unit 4 chimney prepared for wet stack service**











6/7.



- In the most recent environmental upgrade at San Juan Power Station, the Unit 4 chimney with 27,375 ft² of brick flue surface was the first one of four chimneys to be lined with the Pennguard® Block Lining System.

  The chimney contractor, Pullman Power, had to complete the lining of the brick flue and all related works in an outage of 6 weeks, during the third quarter of 2007.
- Before installing the Pennguard<sup>®</sup> lining, the brickwork was power washed and then grit blasted to remove all dirt, deposits and other loose particles.
- 3/4. It is normal for brick flues to show some offsets between the individual bricks.

  The Pennguard® lining can accommodate most of these surface irregularities by using a thicker adhesive back joint.
  - 5. Narrow, stable cracks, caused by settling of the brickwork or thermal shocks, can usually be covered by the Pennguard® Block Lining System without additional preparation.

After grit blasting and application of the Primer onto the brick surface (picture 6), liquid collection gutters were installed into the chimney (picture 7).

Alden Research Laboratory and Pullman Power designed a liquid collection system for each of the four chimneys.




8/9. The Pennguard® Blocks are applied to the brick substrate using the Pennguard® Adhesive Membrane.

The Pennguard® lining installation crew consisted of installers, who were supported by helpers on the platform as well as on ground level. The typical installation productivity is 15 to 21 ft² per installer per hour. All the work, including surface preparation, installation of the liquid collection system, lining application and construction of a false floor was completed within the 6-week outage.





## One project, four chimneys



The similar Unit 3 chimney was the second chimney to be lined and was successfully completed as well, in a 6-week outage, during the first quarter of 2008. The applications in the Unit 1 and Unit 2 chimneys are scheduled in the third quarter of 2008 and the first quarter of 2009. The combined surface area of all chimney flues to be lined is 87,445 ft<sup>2</sup>.

## Installation process summarized:

- Installing work platform
- Cleaning and grit blasting brick substrate
- Brickwork repairs
- Primer application
- Liquid collection system installation
- Pennguard® lining installation
- Finishing works including false floor installation

# Converting brick flues for low temperature FGD service

## Pennguard® linings are the most effective technology

Ever since the introduction of FGD plants, owners have decided to re-use their existing, brick lined chimneys for low temperature, acid condensing operation. Brick flues have been prepared for agressive FGD operating conditions in various ways and Pennguard® linings have proven to be the most effective, durable technology.

### Why?

### A positive barrier

A lightweight, impermeable Pennguard® lining will form a positive barrier, isolating the brick flue from any contact with acidic flue gas and condensate.


Picture 1 shows the outside of a brick flue that was internally lined with Pennguard® and then placed in wet stack service. Picture 2 shows the outside of a brick flue that was left unprotected except for pressurizing the annular space, and then placed in wet stack service.

#### No anchors, no supports

A Pennguard® lining is lightweight and fully bonded to the brick substrate by its adhesive. It does not require any anchors or supports that could lead condensate into the lining and create weak spots as a result of corrosion.

#### Flexible and adaptable

By their nature, most brick flues have irregularities such as bulges, offsets between bricks and narrow cracks. Thanks to the limited size of Pennguard® Blocks and the flexibility of its adhesive, a Pennguard® lining will readily adapt to most of these irregularities.





With the four chimneys at San Juan Generating Station included, Pennguard® linings have been successfully installed in well over 30 brick flues in power stations worldwide.